

Learjet 40/45 Series Maintenance Update

Course Information

Course Description – 5 Day Course

FlightSafety's Learjet 40/45 Series Update Training Course meets the training requirements of technicians / engineers with actual experience on the specific airframe or engine. System Reviews are provided on an as-needed-basis, as indicated by the specific clients.

The latest service information and operational aspects of a safe and efficient dispatch of the aircraft are reviewed and stressed. The technician will be required to utilize technical data as well as recall major system and sub-system normal operations, ground handling, safety precautions, and system self-test procedures.

Technicians attending the update course should have previously completed an initial maintenance course and be familiar with the day to day operation of the airframe and or engine.

FlightSafety Material Number 303954

Ground School Course Modules Hours

| | |
|---|--------------|
| Aircraft Technical Documentation Update | 5.00 |
| Systems Review | 9.50 |
| Operationally Based Troubleshooting | 15.00 |
| Ground School Training Hours | 29.50 |

Academic Course Modules Hours

| | |
|----------------------------|------|
| Welcome/Introduction..... | 0.50 |
| Systems Integration* | 2.00 |
| Brief and Debrief* | 0.50 |
| Review/Exam | 3.00 |

*Based upon availability and course schedule.

Total Hours..... 35.50

Approvals and Limitations

| | |
|----------------------------|----------------------------------|
| FAA IA Renewal Code | C-IND-IM-130406-K-006-017 |
| FAA IA Course Validity: | 03/01/2019 – 04/30/2021 |

Training Locations & Contact Information

Tucson, Arizona • 800-203-5627 • 520-918-7100 • tucson@flightsafety.com