

**Course Description – 5 Day Course**

FlightSafety's Beech 390 Update Training Course meets the training requirements of technicians / engineers with actual experience on the specific airframe or engine. System Reviews are provided on an as-needed-basis, as indicated by the specific clients.

The latest service information and operational aspects of a safe and efficient dispatch of the aircraft are reviewed and stressed. The technician will be required to utilize technical data as well as recall major system and sub-system normal operations, ground handling, safety precautions, and system self-test procedures.

Technicians attending the update course should have previously completed an initial maintenance course and be familiar with the day to day operation of the airframe and or engine.

FlightSafety Material Number .....303957

**Ground School Course Modules                      Hours**

Aircraft Technical Documentation Update .....	5.00
Systems Review .....	9.00
Operationally Based Troubleshooting .....	15.00
<b>Ground School Training Hours .....</b>	<b>29.00</b>

**Academic Course Modules**

Welcome/Introduction.....	1.00
Systems Integration* .....	1.00
Brief/Debrief* .....	0.50
Review/Exam .....	2.00

\*Based upon availability and course schedule.

**Total Hours..... 33.50**

**Approvals and Limitations**

**FAA IA renewal Accepted**  
Accredited for IA refresher training under Title 14 CFR part 65, § 65.93(a)(4)

**Training Locations & Contact Information**

Wichita, Kansas • 800-491-9796 • 316-361-3900 • [wichitamaintenance@flightsafety.com](mailto:wichitamaintenance@flightsafety.com)