

FlightSafety Textron Aviation

TRAINING

Citation Latitude

Course Information

Course Curriculum	Initial	Recurrent	Prior Experience	Indoctrination
Course Module	17 Days	5 Days	6 Days	2 Days
Ground School	42.0 hours	12.5 hours	12.5 hours	8.0 hours
Systems Integration Training	10.0 hours	0.5 hours	0.5 hours	8.0 hours
Briefing/Debriefing	10.5 hours	4.5 hours	6.0 hours	N/A
Simulator (Pilot Flying)	16.5 hours	6.0 hours	8.0 hours	N/A
Simulator (Pilot Monitoring)	16.5 hours	6.0 hours	2.0 hours	N/A

Training Options – The Farnborough Training Center provides only EASA training for this aircraft.

Course Curriculum – The above curriculum as noted is per pilot. Pilot monitoring simulator time will be included should the pilot train as a crew or if paired with another client.

CE680 Type Rated Pilots – FlightSafety has designed a **2-day Latitude Indoctrination Course** for pilots who possess a CE680 type rating, have experience in the Sovereign and are transitioning to the CE680A Latitude. This course is conducted the two days prior to the start of the standard Latitude Recurrent or Prior Experience Course. Pilots attending Recurrent or Prior Experience Courses who have already attended the Latitude Indoctrination Course are not required to attend the Indoctrination Course again, but are welcome to attend for an additional charge.

Prior Experience Course – This course is designed for pilots who are seeking an additional type rating or the addition of an ATP. These pilots must have completed an FAA approved course which led to a type rating prior to enrollment. In addition, this course is also for those pilots who have been flying the aircraft as SIC and now want to obtain a Type Rating. These pilots must have completed an FAA approved pilot initial course and meet the type rating prerequisites.

Type Rating Prerequisites – As a minimum, pilot must possess a multi engine and instrument rating with 1000 hours total time for the CE680A Type Rating.

ATP Prerequisites – FlightSafety is able to administer Airline Transport Certificate (ATP) Checks during the Pilot Initial and Prior Experience Course. To qualify, pilots must meet the requirements of 14CFR Part 61.155 through 61.159.

Course Dates - For course dates, please visit our website at www.flightsafetytextronaviationtraining.com or contact the Learning Center listed below.

Maintenance Training – Maintenance training, including Pratt & Whitney Canada Engine training, is available for this aircraft at our Wichita Maintenance Learning Center.

Training Locations & Contact Information

Columbus, Ohio • 800-896-9563 • 614-559-3700 • columbus@flightsafety.com
Farnborough, United Kingdom • +44-1252-554-500 • farnborough@flightsafety.com
Tampa, Florida • 800-438-2935 • 813-749-5780 • tampa@flightsafety.com
Wichita Cessna, Kansas • 800-488-3214 • 316-220-3100 • cessna@flightsafety.com